




REFERENCE	NI_2013_X98CUP_08_UK
DATE	2013 october 12th
SUBJECT	XAP actuator rebuild

**CONCERNED : 2013 EURO CUP CLIO**

Following the analysis performed by XAP during the Paul Ricard meeting on several gearbox actuators, we confirm you that a rebuild will be necessary.

Referring to the different mileage reached by all the cars of the 2013 paddock, we have determined the mileage between 2 rebuilds as equal to **6000km maximum.**



The rebuild **must** be performed by XAP Electronics, it is strictly **forbidden to do it by yourself** (seals are present on the actuator).

Price of the rebuild: **200€** excl VAT

This price includes:

- Removing, cleaning and re-assembly of all the internal components
- Bearings change
- General inspection of each components
- Performance control on a test bench

Shipment address:

**XAP Technology SAS**  
298, rue des Entrepreneurs  
30420 Calvisson  
FRANCE

**NOTE** : Before sending any actuator, you have to contact the XAP after sales service responsible:

**Samir ALIMOUSSA**  
[alimoussa@xap.fr](mailto:alimoussa@xap.fr)  
(+33) 4 66 02 94 95

