




CLIO R3T
EUROPEAN TROPHY

RENAULT SPORT

CLIO R3T

REFERENCE	BULLETIN TECHNIQUE N°3 / TECHNICAL NEWS N°3
DATE	08 / 09 / 2014
SUBJECT	Conduit Admission / Intake duct
PART	

Suite à un défaut fournisseur, nous tenons à vous communiquer les informations suivantes :



Les bouchons de fermeture (1 et 2) sur le plénum admission présentent un défaut de collage. Nous vous demandons donc de maintenir ces bouchons par :

- Bouchon 1
 - Vis BHC M3 x 20
 - Quantité : 2
 - Localisation : Voir photo + en opposition

- Bouchon 2
 - Vis BHC M3 x 25
 - Quantité : 1
 - Localisation : Marquage Vert sur photo

L'équipe Rallye Renault




CLIO R3T
EUROPEAN TROPHY

RENAULT SPORT

CLIO R3T

Following a supplier default, we would like to inform you about the following information:



The 2 corks on the intake duct present a default. We recommend to add screws in order to maintain the cork in position:

- Cork 1
 - Screw : BHC M3 x 20
 - Quantity : 2
 - Location : see picture + opposite side

- Cork 2
 - Screw : BHC M3 x 25
 - Quantity : 1
 - Location : Green marks on the picture

The Rally Team